R&D Issue: Software release note

Agora Controller 2.3.2

Software revision: 2024, September
Compatible with 3.1.0 G-mk2 config files
Compatible with 2.1.0 Aruba ISeries / Fast 2 / H1 config files
Compatible with 1.0.0 Netgear I Series config files

Compatible with 1.0.3 H-DC firmware and above
Compatible with 1.10.16 Ghost (2,Pi,X) / F2 / H1 firmware and above
Compatible with 1.12.0 G-mk2 firmware and above

Compatible with G-mk2 1.30.0 software image
Compatible with Aruba2930M software image *WC_16_10_0009.swi*
Compatible Netgear software image *M4250H-v13.0.4.23*
Compatible Netgear software image *M4250L-v13.0.4.23*
Compatible Netgear software *M4350-v13.0.4.23*

Software from 2.2.1 to 2.3.2 bug fix:
- RSTP ring topology on G-mk2 is solved in the new software image.

Software 2.3.2 new features improvement:
- Supports the entire range of Netgear M4250 range and Netgear M4350 XSM4328FV model
- AVB switch group mode added Netgear switches
- Allen & Heath gigaACE mode is now extended to Netgear AV Line series with 10Gb Transmit ports

How to make this new version available:

- 1: Execute Agora Controller Installer. If a previous version is already installed, the installer will remove the old one. I many cases you'll have to reboot your computer.
- A G-mk2 firmware update will be required. It will be impossible to downgrade this version later.
- A config update for all series will be required

For detailed information please refer to the software manual.

All the Agora R&D team wishes to thanks all the Beta technicians and all the Pilots for their feedbacks, their trust and loyalty. We do our best for your experience with our products.